



April 23, 2020

Dear Members,

Just after 3:00 PM this afternoon, we experienced gale force winds of up to 41 knots at peak, coming from the North. We inspected the basin for damage, and while there were a number of opportunities for better vessel tie-up and other precautions, it would appear at first inspection that there was no damage to member vessels, dock boxes or tarps, however we did notice that the shrink wrapping on several vessels has come loose.

The main dock systems just past the dolphin, located close to K/L docks and outward, did in fact shift to what looks to be several feet to the South. This movement is believed to be due to the anchor system being under less stress with the current low lake levels. We will be further assessing the situation in full detail tomorrow.

In the mean time, we have temporarily shut off the water to the basin, as there will likely be a break in that system with this substantial movement. If you are out in the basin, please be careful as this movement has caused boards to loosen and nails to pop up in those areas. We apologize for any inconvenience.

Please feel free to contact myself should you have any questions.

Warm regards,

Thom Killingsworth,
Executive Director